

Appendix 1: Flood Event Photographs



Figure 10: Slip on G Burdon's land, The Neck, 1994.



Figure 11: Creek on Burdon's property (1994) at The Neck.



Figure 12: Looking up Makarora valley from the south, 1994.



Figure 13: Clearing SH6, Wharf Creek, 1994.



Figure 14: Wharf Creek, 1994. Figure is seated in the sun roof of vehicle buried by event.



Figure 15: Makarora township (south) and Township Creek, 1994.



Figure 16: Township Creek, 1994.



Figure 17: Flaxmill Creek, 1994.



Figure 18: Flaxmill Creek, north branch (1994).



Figure 19: Cemetery Creek, 1994.



Figure 20: Cemetery Creek looking north, 1994.



Figure 21: Boggy Creek, 1994.



Figure 22: Super-phosphate bin from SH6, Boggy Creek, 1994.



Figure 23: Ewings Creek from SH6, 20th January, 1994.



Figure 24: Water pipeline to intake, Ewings Creek (1994).



Figure 25: Pipson Creek showing SH6 (location of digger) and contributing slip (top right).



Figure 26: SH6 at Pipson Creek, showing debris from the 2006 event.



Figure 27: Debris on true right of Pipson Creek at SH6, showing depth of flows during 2006 event.



Figure 28: Pipson Creek flow depths following 2006 event. Figure's hand is at maximum depth of debris flow. Rock in foreground was deposited during flow. Approximately 150 m upstream of SH6 on true right.