



Photograph 1. Looking North along Lot 2 DP 345184 from existing access on Section 1 SO 22971.



Photograph 3. Concrete path descending north to dirt track within Pt Section 129 Blk XX Shotover SD.



Photograph 2. Looking North from Lot 2 DP 345184 to Pt Section 129 Blk XX Shotover SD and the short section of concrete track.



Photograph 4. Unkempt Steep Grass Embankment within Lot 2 DP 345184 looking North from Section 1 SO 22971.



Photograph 5. Existing Mature Pittosporums and semi mature Beech Trees within Lot 2 DP 345184 adjacent to the existing SEL vehicular access.